
HEATED GEAR & WORKWEAR SIZING CHARTS

MEN'S - REGULAR FIT

Comfortable with room to move.

For best fit, measure body at specified points and match measurement to appropriate size range.

SIZE	S	М	L	XL	XXL
CHEST (cm)	96.5–101.6	101.6-106.7	106.7-111.8	111.8-116.8	116.8-121.9
WAIST (cm)	76.2-81.3	81.3-86.4	86.4-91.4	91.4–96.5	96.5-101.6



WOMEN'S - SLIM FIT

Contours to body shape.

For best fit, measure body at specified points and match measurement to appropriate size range.

SIZE	S	М	L	XL	XXL
CHEST (cm)	83.8-88.9	88.9–94	94–99.1	99.1–104.1	104.1–109.2
WAIST (cm)	71.1–76.2	76.2-81.3	81.3-86.4	86.4–91.4	91.4–96.5
HIPS (cm)	86.4-91.4	91.4–96.5	96.5–101.6	101.6-106.7	106.7–111.8

